

Fall 1975

Monitoring - Pesticides Disposal Sites

Lovelock - Soil (Pershing Co.)

50' North - None
50' East - "
50' South - "
50' West - "

Lovelock - Vegetation

50' North - .002 DDE; .003 H.E.
50' East - None
50' South - .003 DDE; .002 H.E.
50' West - .002 H.E.

Lovelock - Water

(1) Well 1½ miles S.W. - None
(2) Well 2 " S.W. - "

Middle Recse Not in use this season

Orovada - Soil (Humboldt Co.)

50' North - None
50' East - "
50' South - .003 Aldrin
50' West - .001 Aldrin

Orovada - Vegetation

50' North - .004 DDT
50' East - .009 DDT
50' South - None
50' West - "

Orovada - Water

(1) Well 2½ miles S.W. - None
(2) Spring 1-3/4 miles S.W. - None

Fallon - Soil (Churchill Co.)

50' North - None
50' East - "
50' South - "
50' West - "

Fallon - Vegetation

50' North - None
50' East - "
50' South - "
50' West - "

*H.E. = Heptachlor Epoxide

2
Fallon - Water

(1) Well - 1 mile East - None

*Air not monitored at any site.

**All sites inactivated 10-25-75. Use season commences 5-15-76.